



H29.6.19



H29.6.19



H29.6.19



## 恩湯解体状況写真



H29.6.20



H29.6.20



H29.6.20



## 恩湯解体状況写真



H29.6.23



H29.6.23



H29.6.23




## 恩湯解体状況写真



H29.6.27



H29.6.27



H29.6.27



## 恩湯解体状況写真



H29.6.28



H29.6.28



H29.6.28



## 恩湯解体状況写真



H29.7.3



H29.7.3



H29.7.3

# 恩湯解体状況写真



H29.7.5



H29.7.5





## 恩湯解体状況写真




H29.7.8

住吉様 搬出



H29.7.8

住吉様 搬出



H29.7.8

住吉様 搬出



## 恩湯解体状況写真



H29.7.11

女湯浴槽



H29.7.11

新規泉源(?)が出現



H29.7.11

新規泉源(?)が出現



## 恩湯解体状況写真



H29.7.13



H29.7.13

男湯浴槽の養生



H29.7.13

恩湯泉源が出現



## 恩湯解体状況写真



H29.7.13

恩湯泉源



H29.7.13

恩湯泉源



H29.7.13

恩湯泉源



## 恩湯解体状況写真



H29.7.18

男湯下湧出泉源調査



H29.7.18

男湯下湧出泉源調査



H29.7.18

男湯下湧出泉源調査